

N61165.AR.005276  
CNC CHARLESTON  
5090.3a

LETTER REGARDING SOUTH CAROLINA DEPARTMENT OF HEALTH AND  
ENVIRONMENTAL CONTROL REQUEST FOR ACTION FOR BUILDINGS NS-45 AND NS-  
44A CNC CHARLESTON SC  
01/05/2006  
SOUTH CAROLINA DEPARTMENT OF HEALTH AND ENVIRONMENTAL CONTROL

BOARD:  
Elizabeth M. Hagood  
Chairman  
Edwin H. Cooper, III  
Vice Chairman  
Steven G. Kisner  
Secretary



C. Earl Hunter, Commissioner

*Promoting and protecting the health of the public and the environment.*

BOARD:  
Henry C. Scott  
Paul C. Aughtry, III  
Glenn A. McCall  
Coleman F. Buckhouse, MD

5 January 2006

Commander  
NAVFACENGCOM Southern Division  
Attn: Code ES24 (Gabriel Magwood)  
P.O. Box 190010  
North Charleston, SC 29419-9010

Re: CNB – BLDG's NS45 and NS44A  
**Site Identification #'s 17787 and 17779**  
Request for Action  
Charleston County

Dear Mr. Magwood:

SOUTHDIV submitted a sampling and analysis plan dated 13 June 1997 to investigate the petroleum problems at these two sites (the tank systems were adjacent to each other). Specifically, Arsenic and Lead were identified in groundwater associated with UST NS44A and SVOCs were detected in groundwater above RBSLs for NS45. Our records reveal that the Department approved the SAP, but no final report was ever submitted. In addition, I can find no record that the Department ever concurred, or was notified, that the sites were transferred into the RCRA program.

If SOUTHDIV feels that this area has been adequately investigated for the confirmed petroleum problems, SOUTHDIV should submit a brief data package that clearly shows when and where samples were taken and analyzed for petroleum constituents in the vicinity of these former USTs. Absent this data we consider these sites active.

In the event that SOUTHDIV cannot provide sufficient information pertaining to the investigation of these sites, the Department requests that a work plan be submitted outlining proposed investigative activities.

Please submit the requested documentation or the proposed work plan to the Department no later than 31 March 2005. Should you have any questions, please contact me at 803-898-3553 (office phone), 803-898-3795 (fax) or [bishopma@dhec.sc.gov](mailto:bishopma@dhec.sc.gov).

Sincerely,

Michael Bishop, Hydrogeologist  
Groundwater Quality Section  
Bureau of Water

cc: Region 7 District EQC  
Jerry Stamps – BLWM  
Technical File